

## YSHIELD® GCS | Grounding connection Screw

Grounding connection with two plates that get screwed together. For all electrically conductive fabrics, fleeces, meshes.

---



Grounding connection with two plates that get screwed together. For all electrically conductive fabrics, fleeces, meshes. **The two connecting plates must be screwed together - the material that is supposed to be grounded needs therefore to be perforated.**

- Connectivity: 1 cable connection
- Scope of delivery: 2 connecting plates 36x36x6 mm, all necessary screws, discs, cables lugs and a screwing tool with Torx®-Bits. Cable is not included in the scope of delivery - we recommend our pre-assembled grounding cables GL.

YSHIELD GmbH & Co. KG  
94099 Ruhstorf, Germany  
**[www.yshield.com](http://www.yshield.com)**  
**[info@yshield.de](mailto:info@yshield.de)**